

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

RECEIVED

JAN 21 2000

DIVISION OF
OIL, GAS AND MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/99 To (mo./yr.) 12/99
 2. DOGM File Number (Mine No): M / 45 / 030
 3. Mine Name: Timpie Solar Ponds
 4. Mineral(s) Mined (or permitted to mine): Salt NACL
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
NW 1/4, NE 1/4, 1/4, Section 8, Township 1S, Range 7W
1/4, 1/4, 1/4, Section , Township , Range
1/4, 1/4, 1/4, Section , Township , Range
 7. Name of Operator or Company: Cargill Salt Inc.
 8. Permanent Street Address: PO Box 648
City, State, Zip: Grantsville, UT. 84029
Phone: 435-884-0123 Fax: 435-884-0922
 9. Company Representative (or designated operator):
Name: Lyndon Jones
Title: Plant Manager
Business Address: 15100 West Rowley Road
City, State, Zip: Grantsville, UT. 84029
Phone: 435-884-0123 Fax: 435-884-0922
- ☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? 570,000 ST

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
18,480 Linear feet of dike was constructed in side of
one pond.
73,920 Cu. yard of material was borrowed from along
side the dikes.
5. How much **additional acreage** was disturbed during the past year? _____
6. How much acreage was **reclaimed** during the past year? _____
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
 _____ N/A

8. What is the **total** disturbed acreage of entire project at years end? 20 acres
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
We will be building 2 more dikes inside of our ponds
that will consist of borrowing 36,000 Cu. yard of
material.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Lyndon Jones

Title of Operator:

Plant Manager

Signature of Operator:

Date:

1/19/00

02064
5/19/99

11/045/030

SALT DIVISION

PO Box 648
Grantsville, UT 84029
435/884-4131 Fax: 435/884-6518

Patrick M. Donovan
Maintenance Supervisor
Plant Engineer



CARGILL SALT DIVISION

PO Box 648
Grantsville, UT 84029
435/884-4147 435/884-0123 Ext 147

Lyndon T. Jones
Plant Manager - Timpie, UT Facility
Fax: 435/884-0922